Nickel West Leinster Water Services Licence WL52



Post Audit / Review Implementation Plan

26 February 2025

Table of Contents

Document Control	2
Introduction	3
Operational Audit and Review	4

DOCUMENT CONTROL

Date	Document Issue	Details	Authored
01/06/2023	Original Issue	N/A	Manager HSE
04/07/2023	V2.0	Amended following ERA feedback	Manager HSE

BHP Nickel West Page 2 of 5

INTRODUCTION

In accordance with Condition 5.3 of Water Services Licence WL52, an Operational Audit was undertaken with respect to drinking water and sewerage services to the township of Leinster. The audit was undertaken by independent experts **Quantum Assurance**, appointed by the Economic Regulation Authority (ERA). The audit report was provided to BHP on 25 February 2025.

As required by the 2019 Audit and Review Guidelines (ERA), BHP is required to submit a Post Audit Review Implementation Plan (PARIP), detailing the proposed actions to address recommendations made in the Operational Audit.

BHP Nickel West Page 3 of 5

OPERATIONAL AUDIT AND REVIEW

Table One details the actions proposed to address non-compliances and recommendations arising from the Operational Audit and Review.

Table 1 - Post Audit / Review Implementation Plan

Recommendation reference Non-compliant	ance / Controls improvement	Auditors' recommendation	Action proposed to be taken by the licensee	Responsible person(s)	Completion date
Recommendation 1/2024 Recommendation 1/2024	on mentioned in clause 54(1)(a) or to be recorded on a register art; is for applying to be recorded on a er that Part; ions placed on the licensee under ne event of a service interruption." states "This clause applies if a eives notice or otherwise omes aware that a person who des at a supply address requires er for the operation of a dialysis chine or other life support ipment; or esses and determines that a son who resides at a supply less requires water for a special dof another kind."	BHP Nickel West should include information for customers with special needs for water, about how to apply for inclusion in the Preserved Supply Register and the obligations of BHP in the event of a service interruption.	BHP to add notice information regarding the Preserved Supply Register onto the BHP website.	Health Safety Security and Emergency Management Superintendent	Completed

	This audit confirmed that the Preserved Supply Register was set up in February 2024, including customer engagement to inform the initial population of the Preserved Supply Register. There were zero nominations received through the customer engagement. The audit sighted the Preserved Supply Register with zero nominations. As there has been no nominations in the audit period, this is considered a minor noncompliance.				
Recommendation 2/2024	Licensing Payments to ERA Rating: A2 Obligation 155 – The licensee must pay the applicable fees and charges in accordance with the Economic Regulation Authority (Licensing Funding) Regulation 2014. The fee for 2023/24 due by 30 September 2024 was not paid until November 2024. As the payment was overdue, this is considered a non-compliance with minor impact and did not affect customers.	BHP should include a reminder in the Corporate Calendar to ensure that ERA invoices are paid by the due date.	ERA invoices are paid in a different format than standard invoices at BHP. This process has since been rectified to prevent delays in payment and is stored on our Water License folder for future use and reference.	Health Safety Security and Emergency Management Superintendent	Completed
	The payment was overdue due to an incorrect purchase order number. The reminder is included in the Compliance Register.				

BHP Nickel West Page 5 of 5